

Place

Commercial Services

PROPERTY MANAGEMENT

COUNCIL HEADQUARTERS, NEWTOWN ST BOSWELLS, TD6 0SA

Telephone 01835 824000 Fax 01835 825061

Head of Service - Andrew Drummond-Hunt

Condition Survey Report

Property: Linglie Farm UPRN: SK033/06

Surveyed By: Lynn Thomson, Gordon Horsburgh, Tom Holmes

Survey Date: 25th August 2014

Report By: Lynn Thomson, Gordon Horsburgh

Report Date: 6th Oct 2014

PLEASE NOTE: THIS SURVEY IS FOR INDICATIVE PURPOSES ONLY. ALL COSTS

SUBJECT TO CHANGE - QUOTATIONS SHOULD BE OBTAINED.

Property Description & Construction:

Traditional Stone construction farmhouse with pitched slate roof and new upvc double glazed windows. The farm buildings consist of traditional stone construction steading/stable buildings with pitched metal profile and slate roofs. Other single skin profile metal sheet timber portal frame storage buildings and a more recent steel portal frame farm building. There are also two semi-detached single storey traditional brick built farm cottages with pitched cement tiled roofs and partial new upvc double glazing.

Summary:

Survey is visual and non-intrusive. No survey or cost included for fire safety, asbestos, DDA. No access to roof voids. Survey not structural. Cost excluding any fees & VAT.